











change to make potentiometer attenuate the CV input?



change to make potentiometer attenuate the CV input?



5 volt reference (could be removed?)



Powering the OpAmps

